

AD-A156 848


NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
BAKER FLOODWATER RESE. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV JUL 79

1/1

UNCLASSIFIED

F/G 13/13


NL



END

FILED

10/1



MICROCOPY RESOLUTION TEST CHART  
 NATIONAL BUREAU OF STANDARDS-1963-A

AD-A156 840

MERRIMACK RIVER BASIN  
WENTWORTH, NEW HAMPSHIRE

**BAKER FLOODWATER RESERVOIR  
SITE 11  
NH 00478**

NHWRB NO. 249.13

**PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM**

DTIC  
ELECTE  
JUL 17 1985  
S D  
G



**DISTRIBUTION STATEMENT A**

Approved for public release  
Distribution Unlimited

**DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154**

**DTIC FILE COPY**

**JULY 1979**

**85 06 26 003**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

ADA 156 840

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NH 00478	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Baker Floodwater Reservoir Site 11 NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE July 19, 1979
		13. NUMBER OF PAGES 65
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Merrimack River Basin Wentworth, New Hampshire Tributary to Baker River		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) The dam is a 681 ft. long 24 ft. high earthen structure. The dam is judged to be in good condition. There were a few items noted during the inspection which require attention. It is small in size with a significant hazard potential. There are no other recommendations resulting from the inspection.		

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
424 TRAPELO ROAD  
WALTHAM, MASSACHUSETTS 02154

REPLY TO  
ATTENTION OF:  
NEDED

JAN 17 1980

Honorable Hugh J. Gallen  
Governor of the State of New Hampshire  
State House  
Concord, New Hampshire 03301

Dear Governor Gallen:

Inclosed is a copy of the Baker Floodwater Reservoir Site 11 Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Water Resources Board, the cooperating agency for the State of New Hampshire and the owner of the dam.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for your cooperation in carrying out this program.

Sincerely,

*Max B. Scheider*  
MAX B. SCHEIDER

Colonel, Corps of Engineers  
Division Engineer

Incl  
As stated

BAKER FLOODWATER RESERVOIR SITE 11

NH 00478

NHWRB 249.13

MERRIMACK RIVER BASIN  
WENTWORTH, NEW HAMPSHIRE

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/	

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



LETTER OF TRANSMITTAL  
FROM THE CORPS OF ENGINEERS TO THE STATE  
TO BE SUPPLIED BY THE CORPS OF ENGINEERS



NATIONAL DAM INSPECTION PROGRAM  
PHASE I - INSPECTION REPORT  
BRIEF ASSESSMENT

Identification No.: 00478  
Name of Dam: Baker Floodwater Reservoir Site 11  
Town: Wentworth  
County and State: Grafton, New Hampshire  
Stream: Tributary to Baker River  
Date of Inspection: May 17, 1979


Baker Floodwater Reservoir Site 11 is a 681 foot long 24 foot high earthen structure. There are two different fill zones in the dam including a cut off wall. Top width of the dam is 12 feet. The upstream and downstream embankments are on a 3 horizontal to 1 vertical slope. Appurtenant structures consist of a principal spillway, plunge pool stilling basin, emergency spillway, and a 8 inch diameter gated pond drain. The principal spillway has two inlets, a low stage orifice and a high stage covered top spillway. The inlets discharge through the riser to a 2.5 foot diameter concrete pipe. The dam construction was completed in November of 1971. Plans, design calculations and construction data were prepared by the Soil Conservation Service and are available for inspection.

The visual inspection revealed that the dam is in good condition. Items noted during the inspection are staining and scaling of the concrete riser structure, log debris along the reservoir shoreline, and a large fallen tree in the downstream channel.

Based on the small size of the dam and its significant hazard classification and in accordance with Corps of Engineers guidelines, the test flood inflow should be of a magnitude between the 100 year frequency flood and 1/2 the Probable Maximum Flood (PMF). The test flood inflow used is equal to 1/2 the PMF or 825 cfs. The routed test flood outflow of 495 cfs does not overtop the dam as the capacity of the spillways is 607 cfs. There will be a freeboard of 0.4 feet. The design hydraulic calculations indicate that the principal spillway was designed for a 100 year frequency flood. The crest elevation of the dam was designed using a watershed runoff of 6.9 inches.

There are no recommendations resulting from the Phase I Inspection. Remedial measures include the development of a downstream warning system and removal of log debris from the reservoir and downstream channel, and removal of logs downstream of the emergency spillway.


The remedial measures are described in Section 7 and should be completed within two years of the receipt of this report by the owner.





*Gordon H. Slaney, Jr.*  
Gordon H. Slaney, Jr., P.E.  
Project Engineer

Howard, Needles, Tammen & Bergendoff  
Boston, Massachusetts

This Phase I Inspection Report on Baker Floodwater Reservoir Site 11 has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgement and practice, and is hereby submitted for approval.

  
JOSEPH W. FINEGAN, JR., MEMBER  
Water Control Branch  
Engineering Division

  
CARNEY M. TERZIAN, MEMBER  
Design Branch  
Engineering Division

  
JOSEPH A. MCELROY, CHAIRMAN  
Chief, NED Materials Testing Lab.  
Foundations & Materials Branch  
Engineering Division

APPROVAL RECOMMENDED:

  
JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

## TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

## REPORT

1. PROJECT INFORMATION	1-1
1.1 General	1-1
a. Authority	1-1
b. Purpose of Inspection	1-1
1.2 Description of Project	1-1
a. Location	1-1
b. Description of Dam and Appurtenances	1-2
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-2
f. Operator	1-2
g. Purpose of Dam	1-3
h. Design and Construction History	1-3
i. Normal Operational Procedure	1-3
1.3 Pertinent Data	
2. ENGINEERING DATA	2-1
2.1 Design Data	2-1
2.2 Construction Data	2-1
2.3 Operation Data	2-1
2.4 Evaluation of Data	2-1

<u>Section</u>	<u>Page</u>
3. VISUAL INSPECTION	3-1
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-2
d. Reservoir Area	3-3
e. Downstream Channel	3-3
3.2 Evaluation	3-3
4. OPERATIONAL PROCEDURES	4-1
4.1 Procedures	4-1
4.2 Maintenance of Dam	4-1
4.3 Maintenance of Operating Facilities	4-1
4.4 Description of any Warning System in Effect	4-1
4.5 Evaluation	4-1
5. HYDRAULIC/HYDROLOGY	5-1
5.1 Evaluation of Features	5-1
a. General	5-1
b. Design Data	5-1
c. Experience Data	5-1
d. Visual Observation	5-1
e. Overtopping Potential	5-1
f. Dam Failure Analysis	5-2
6. STRUCTURAL STABILITY	6-1
6.1 Evaluation of Structural Stability	6-1
a. Visual Observation	6-1
b. Design and Construction Data	6-1
c. Operating Records	6-1
d. Post-Construction Changes	6-1
e. Seismic Stability	6-1

## SECTION 4 OPERATIONAL PROCEDURES

### 4.1 Procedure

Baker Dam Site 11 is used for floodwater control. The normal pool level is maintained by the low stage orifice opening in the riser. Flood events of up to a 100 year frequency are retarded by the reservoir storage between the normal pool and the emergency spillway crest. The emergency spillway is utilized for events of greater than 100 year frequency.

### 4.2 Maintenance of Dam

The dam is inspected on an annual basis by the New Hampshire Water Resources Board and the Soil Conservation Service. Maintenance is undertaken as a result of the inspection on an as needed basis. The dam is visited on a regular monthly basis by personnel of the owner.

### 4.3 Maintenance of Operating Facilities

Maintenance of the outlet works is performed as in Section 4.2.

### 4.4 Description of Warning Systems

There are no warning systems in effect for this facility.

### 4.5 Evaluation

The current operation and maintenance procedure for this facility appear to be adequate to insure that any problems encountered can be remedied within a reasonable period of time. However, the owner should establish a warning system to follow in the event of emergency conditions.

The pond drain structure consists of a 8 inch diameter pipe and an intake with a trash rack. The drain discharges to the riser where it is gated with a 8 inch gate valve. The intake, pipe and valve could not be inspected as they were under water at the time of inspection. The operating mechanism located on top of the riser appeared to be in operational condition.

The 30 inch reinforced concrete discharge pipe, concrete cradle and supporting pier at the toe of the dam are in good condition as seen in Photos No. 12 & 13.

d. Reservoir Area. The area around the reservoir is mostly wooded. There are no cottages or dwellings along the shoreline. A roadway runs along the left bank of the reservoir. The shoreline is lined with many fallen trees.

e. Downstream Channel. Below the outlet works the channel has a natural rock strewn bed, with grassed banks. About 100 feet downstream of the dam the channel enters a wooded area. At this point there is a large fallen tree crossing the channel.

### 3.2 Evaluation

Visual examination indicates the dam is in good condition. Visual examination revealed the following:

- (a) Some surface scaling and water staining on the concrete riser structure.
- (b) Log debris along the reservoir banks.
- (c) A large fallen tree across the downstream channel.
- (d) Logs and fallen trees at the downstream end of the emergency spillway.



### Downstream Slope

The downstream slope is 3 horizontal and 1 vertical and has an excellent grass cover as shown in Photo No. 4. The contact between the downstream slope and the abutments has been paved with riprap to prevent erosion. This riprap is in excellent condition.

No seepage or damp areas were observed on the downstream slope or below the toe of the dam.

The dam has a 4 foot wide trench drain near the downstream toe which is piped to the outlet stilling basin. A small amount of water was flowing from the 12 inch diameter drainpipe exiting on the left side of the outlet pipe.

c. Appurtenant Structures. The visual inspection of concrete riser spillway structure, auxiliary earth spillway and outlet works structure did not reveal any evidence of stability problems with respect to sliding and overturning.

The concrete surface of the riser structure generally appeared to be in good condition except for concrete water staining and some surface scaling see (Photo No. 7). The spillway trash racks are also in good condition; no rust or peeling of the protective coating was noted.

The principal spillway structure consists of three elements, an overflow control with low stage inlet and high stage spillway crest, a vertical transition and a closed discharge conduit. The riser structure is placed in the embankment. Visual inspection revealed that the riser structure appeared to be in good condition except for some surface mortar loss and water staining, see Photo No. 7.

The trash racks at the low and high stage inlets consist of standard shape angles and grating.

Both trash rack assemblies are in good condition.

The emergency earth spillway structure in Photos No. 8, 9 & 10 is located at right abutment. The earth spillway is a relatively flat grassy area and is formed by the natural hill on the right side and the dam embankment to the left. The emergency spillway leads to downstream channel.

There are a few wet areas in the emergency spillway which are shown in Photo No. 10. Logs and fallen trees were seen at the downstream end of the emergency spillway.

SECTION 3  
VISUAL INSPECTION

3.1 Findings

a. General. The field inspection of Baker Dam Site 11 was made on May 17, 1979. The inspection team consisted of personnel from Howard, Needles, Tammen & Bergendoff and Geotechnical Engineers, Inc. A representative of the New Hampshire Water Resources Board was also present during the inspection. Inspection checklists, completed during the inspection, are included in Appendix A. At the time of inspection the water level was approximately 0.3 feet above the invert of the low stage inlet. The upstream face of the dam could only be inspected above this water level.

b. Dam. Visual inspection of the dam indicated that it is in good condition.

The dam, completed in 1971, is an earth embankment about 681 feet long and about 24 feet high. The embankment consists of two zones, a wide central core of silty fine to medium sand and upstream and downstream shells of sandy gravel. A cutoff trench 12 feet wide at its base extends below the axis of the dam into bedrock or an impervious silty till. A 4 foot wide drainage trench extends below the downstream shell at the base and the abutments of the dam.

An unpaved emergency spillway is cut into the right abutment passing around the embankment. An outlet works consisting of a concrete riser, 30-inch diameter concrete pipe passing through the dam, and a riprap lined stilling basin is located in line with the original stream channel.

Upstream Slope

The upstream slope is 3 horizontal to 1 vertical and has a 10 foot wide berm at about elevation 668, about 15 feet below the crest. The slope shown in Photo No. 2 is grass covered and in good condition.

Riprap placed around the intake structure was below the water level and could not be inspected.

Crest

The crest of the dam, which is shown in Photo No. 3, is 12 feet wide and has an excellent grass cover.

No misalignment of the crest was observed.

## SECTION 2 ENGINEERING DATA

### 2.1 Design

A complete set of design data including layout, hydraulic design, foundation and embankment design, geology and soils reports, structural design, quantities and specifications are available for Baker Dam Site 11. In addition, there are construction drawings available. Design of the dam was done by the Soil Conservation Service, Durham, New Hampshire.

### 2.2 Construction

The dam construction was completed in November of 1971. A complete record of construction documents were made available. These documents include; as-built plans; job diaries, surveying records, test drilling logs, compaction test results, concrete tests and certificates of completion. Construction was by Robie Construction Co., Inc. and was inspected by the Soil Conservation Service, Durham, New Hampshire.

### 2.3 Operation

Normally the pond drain line gate is closed. The normal level of 667.0 is maintained by the low stage orifice openings. The principal spillway riser and reservoir storage is designed to retard runoff from up to a 100 year frequency storm without discharge occurring in the emergency spillway. (crest 680.5)

### 2.4 Evaluation

a. Availability. Engineering data available for Baker Dam Site 11 consists of the information outlined in Sections 2.1 and 2.2. The plans, design data, and construction records are available at the offices of the Soil Conservation Service, Federal Building, Durham, New Hampshire, 03824.

b. Adequacy. A complete set of design and construction data did allow for a definitive review within the confines of this Phase I - Inspection Report. Therefore, the adequacy of this dam is based on the design and construction data reviewed, visual inspection, past performance history and sound engineering judgement.

c. Validity. The field inspection indicated that the external features of Baker Dam Site 11 substantially agree with those shown on the available plans.

### Emergency Spillway

- (1) Type - earth
- (2) Length of Weir - 80 feet wide
- (3) Crest Elevation - 680.5
- (4) Gates - none
- (5) U/S Channel - Approach channel from reservoir is 80 feet wide with  $2\frac{1}{2}$  to 1 side slopes

(6) Downstream Channel - Below the outlet works the channel has a natural rock strewn bed, with grassed banks. About 100 feet downstream of the dam the channel enters a wooded area. At this point there is a large fallen tree crossing the channel.

j. Regulating Outlets. The normal level of the reservoir is controlled by a 11.25 inch by 9 inch orifice inlet set in the riser at invert elevation 667.0. There is a trash rack for the opening but no control gate. The 8 inch pond drain pipe set at invert 657.5 extends 22 feet into the reservoir from the riser, and has a trash rack at the intake. The pipe is controlled at the riser by a gate.

f. Reservoir Surface (acres)

- (1) Normal Pool - 2.8
- (2) Flood Control Pool - 9.4
- (3) Emergency Spillway Crest - 9.8
- (4) Test Flood Pool - 13.0
- (5) Top Dam - 13.0

g. Dam

- (1) Type - earth
- (2) Length - 681 feet
- (3) Height - 24 feet hydraulic  
30 feet structural
- (4) Top Width - 12 feet
- (5) Side Slopes - upstream and downstream 3 horizontal  
to 1 vertical
- (6) Zoning - 2 fill zones
- (7) Impervious core - none
- (8) Cutoff - zone 1 fill
- (9) Grout Curtain - none
- (10) Other - none

h. Diversion and Regulating Tunnel

See Section j

i. Principal Spillway

- (1) Type - concrete riser, covered top
- (2) Length of Weir - total 15 feet
- (3) Crest Elevation - 679.12
- (4) Gates - Discharge pipe diameter is 2.5 feet
- (5) U/S Channel - none

(2) There are no records available of maximum discharge at the site. However, during the inspection of the dam on May 17, 1979 it was noted that debris on the face of the dam reached to about elevation 675.4 which would correspond to a discharge of about 7 cfs.

(3) The spillway and riser capacity with the water surface at the top of the dam is approximately 607 cfs at elevation 683.5.

(4) Spillway and riser capacity with the water surface elevation at the test flood elevation of 683.1 feet is approximately 495 cfs.

(5) The total project discharge at the test flood elevation of 683.1 is 495 cfs.

c. Elevation (feet above MSL)

- (1) Streambed at centerline of dam - 659.5
- (2) Maximum tailwater - unknown
- (3) Upstream portal invert pond drain - 657.5
- (4) Normal pool - 667.0
- (5) Full flood control pool - 680.0
- (6) Spillway crest (riser crest) - 679.12  
(emergency spillway) - 680.5
- (7) Design surcharge - 680.0
- (8) Top Dam - 683.5
- (9) Test Flood Surcharge - 683.1

d. Reservoir (miles)

- (1) Length of Maximum Pool - 0.35
- (2) Length of Normal Pool - 0.1
- (3) Length of Flood Control Pool - 0.2

e. Storage (gross acre-feet)

- (1) Normal Pool - 8
- (2) Flood Control Pool - 85
- (3) Spillway Crest Pool - 90
- (4) Top of Dam - 125

g. Purpose of Dam. This dam is used for floodwater control. The normal pool is maintained by the low stage intake in the riser. The storage between the low stage outlet and the emergency spillway crest is used for floodwater control for floods of up to a 100 year frequency.

h. Design and Construction History. The construction of this dam was completed in November of 1971. Design and construction inspection of this dam were done by the Soil Conservation Service, Durham, New Hampshire. The construction contractor was Robie Construction Company, Inc.

i. Normal Operating Procedures. The normal pool is maintained by the low stage inlet on the riser. Under flood conditions, when the capacity of the low stage orifice is exceeded, the storage is utilized. The high stage outlet will reach maximum design discharge before the reservoir reaches the crest of the emergency spillway. The dam does not require any manual operation in order to function.

### 1.3 Pertinent Data

a. Drainage Area. The area tributary to Baker Site consists of 0.55 square miles of mountainous terrain. There is no development in the watershed, which is within the White Mountain National Forest. Maximum elevation is at about 2060 feet MSL, and the dam crest elevation is 683.5 feet.

The area around the reservoir is mostly wooded. There are no cottages or dwellings along the shoreline. A roadway runs along the left bank of the reservoir. The reservoir bank is lined with many fallen trees.

#### b. Discharge of Dam Site

(1) Outlet works for Baker Dam Site 11 consist of an emergency spillway, a riser with a low stage orifice and a high stage covered top spillway, and an 8 inch pond drain pipe controlled by a gate. Invert of the pond drain is at elevation 657.5. Maximum discharge of the pipe when the reservoir is at the normal pool level of 667.0 is about 7 cfs. The low stage orifice has one opening 11.25 inches by 9 inches in size set at invert 667.0. Capacity of the low stage inlet when the reservoir is at the crest of the high stage inlet (679.12) is 9 cfs. The high stage covered inlet crest set at elevation 679.12 has a capacity of 99 cfs when the water level is at the emergency spillway crest of 680.5. The 50 foot wide emergency spillway has a crest at elevation 680.5. When the water surface is at the top of dam (elevation 683.5) the emergency spillway will have a capacity of 500 cfs.

b. Description of Dam and Appurtenances. Baker Site 11 Dam is an earthen embankment structure. Total length of the dam, according to existing drawings, is 681 feet. Maximum structural height is 30 feet, and the maximum height from the top of embankment to the streambed is 24 feet. According to the plans there are two different fill zones in the structure, which include a cut off wall. Top width of the dam is 12 feet and the embankment is on a 3 horizontal to 1 vertical slope both up and downstream.

Appurtenant structures consist of a concrete riser and pipe principal spillway with a covered top inlet. There are two stages to the inlet structure, a low stage orifice and a high stage covered inlet. The riser discharges through a 2.5 foot diameter concrete pipe and a plunge pool type stilling basin. The emergency spillway is located on the right side of the dam and has a width of 50 feet. A 8 inch diameter pond drain pipe can be opened from the riser structure by an 8 inch gate valve to lower the water level.

Figures 1 and 2, located in Appendix B, show a plan of the dam and appurtenant structures. Photographs of each structure are shown in Appendix C.

c. Size Classification. Small (hydraulic height - 24 feet, storage - 125 acre-feet) classification based on height being less than 40 feet, and storage being less than 1000 acre feet as given in Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification. The potential for hazard posed by this dam is classified as significant. Failure of this dam at maximum pool elevation (top of dam) would result in a average flood wave about 15 feet high through the reach studied, extending to .5 miles downstream of the dam. Two dwellings and a commercial building in the reach would be flooded, and two roads would be overtopped.

e. Ownership. This dam is owned by the New Hampshire Water Resources Board, 37 Pleasant Street, Concord, New Hampshire.

f. Operator. This dam is maintained and operated by the New Hampshire Water Resources Board. Chairman of the Water Resources Board is Mr. George McGee, Sr.; Mr. Vernon Knowlton is Chief Engineer, Telephone No. 603/271-1110.



NATIONAL DAM INSPECTION PROGRAM  
PHASE I INSPECTION REPORT  
BAKER FLOODWATER RESERVOIR SITE 11

SECTION 1  
PROJECT INFORMATION

1.1 General

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Howard, Needles, Tammen & Bergendoff has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire Authorization and notice to proceed were issued to Howard, Needles, Tammen & Bergendoff under a letter of March 30, 1979 from John P. Chandler, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0060 has been assigned by the Corps of Engineers for this work.

b. Purpose


(1) To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.


(2) To encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location. Baker Floodwater Reservoir Site 11 (Baker Dam Site 11) is located on a tributary to the Baker River approximately 2500 feet upstream of Routes 25-118 in the Town of Wentworth, New Hampshire. The dam is shown on U.S.G.S. Quadrangle Wentworth, New Hampshire, with approximate coordinates N43°51'55" W71°54'00" Grafton County, New Hampshire. The location of Baker Dam Site 11 is shown on the preceeding page.





<u>Section</u>	<u>Page</u>
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	7-1
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
d. Need for Additional Investigation	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-1
7.4 Alternatives	7-1

#### APPENDIXES

APPENDIX A - INSPECTION CHECKLIST

APPENDIX B - ENGINEERING DATA

APPENDIX C - PHOTOGRAPHS

APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS

APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL  
INVENTORY OF DAMS

SECTION 5  
HYDROLOGY AND HYDRAULIC ANALYSIS

5.1 Evaluation of Features

a. General. Baker Dam Site 11 is an earthen embankment dam 681 feet long with a hydraulic height of 24 feet. The dam is constructed with two fill zones and a earth fill core. Appurtenant works consist of a two stage riser and a 2.5 foot diameter concrete pipe which discharges to a plunge pool type stilling basin. An emergency spillway 50 feet wide is located at the right abutment. There is an 8 inch diameter gated pond drain pipe, discharging to the riser structure.

b. Design Data. According to the Soil Conservation Service design data this dam is constructed to retard flood flows of a 100 year frequency storm without utilizing the emergency spillway. The design flood control elevation is 680.0 or 0.5 feet below the emergency spillway crest. Total runoff for this condition is 2.95 inches during a six hour Type IIB storm. The crest elevation of the dam was designed using a watershed runoff depth of 6.9 inches. The structure is classified as having a "B" hazard which is defined as being located in a predominantly rural and agricultural area, where failure may cause damage to isolated homes, main highways or railroads or cause interruption of use or service of relatively important public utilities.

c. Experience Data. There are no records available of maximum discharge at the dam site. However during the inspection of the dam on May 17, 1979 it was noted that debris on the face of the dam reached to about elevation 675.4 which would correspond to a discharge of about 7 cfs.

d. Visual Observations. No evidence of damage to any portion of the project from overtopping was visible at the time of inspection.

e. Test Flood Analysis. Detailed design data is available for this dam, and the basic conditions are noted above in Paragraph b. The hydrologic evaluation was preformed using information gathered by field investigation, watershed characteristics and Probable Maximum Flood (PMF) guide curves prepared by the Corps of Engineers. In accordance with Corps of Engineers guidelines, the significant hazard classification and small size of the dam warrant a test flood magnitude ranging from the 100 year frequency flood to 1/2 the PMF. A test flood of 1/2 the PMF was used as the hazard classification is on the higher end of the range with two buildings and two roadways affected. A test flood inflow of 825 cfs is based on a drainage area of 0.55 square miles in mountainous terrain.

The routed test flood outflow was determined in accordance with Corps of Engineers guidance for Estimating Effect of Surcharge Storage on Maximum Probable Discharge, and the hydraulic characteristics of the dam. Discharge through both the primary spillway and emergency spillway was considered. The routing was started with the water surface at the normal pool elevation. The routed test flood outflow was determined to be approximately 495 cfs. As the maximum capacity of the spillways is 607 cfs, there will be a freeboard of 0.4 feet.

f. Dam Failure Analysis. The impact of failure of the dam was assessed using the "Rule of Thumb" Guidance for Estimating Downstream Dam Failure Hydrographs prepared by the Corps of Engineers. The breach discharge was estimated with the water surface at the crest of the dam and a breach width equal to 40 percent of the total length of the dam. The downstream hydrograph is a sum of the breach discharge and the maximum spillway capacity. Prior to the breach of dam the downstream river stage would be about 9 feet the spillways at a full capacity of 607 cfs. Breach of dam would result in an additional 32,100 cfs for a total of about 32,700 cfs. The downstream flood stage was estimated through two reaches for a total distance of 0.5 miles from the dam to Route 25-118. The floodwave would be about 17 feet high at the dam and 12.8 feet at the Route 25-118 bridge. Near the bridge there are two dwellings set about 7 feet above the channel and one commercial building set about 6 feet above the streambed. All of these buildings are at least 200 feet from the main stream channel. In addition, Buffalo Road located just downstream of the dam and 6 feet above the streambed would be overtopped. Route 25-118 would also be overtopped as it is set 8.5 feet above the streambed.

SECTION 6  
STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations. The visual inspection of Baker Dam Site 11 did not disclose any immediate stability problems.

b. Design and Construction Data. Design drawings and construction specifications exist and indicate the dam is a zoned embankment consisting of a wide central core of silty fine to medium sand and downstream and upstream zones of sandy gravel. A cutoff trench extends below the central portion of the dam. The cutoff trench extends up both abutments. The upstream and downstream slopes are 3 horizontal and 1 vertical.

A drainage trench is located beneath the downstream zone of the embankment.

A grass-covered emergency spillway passes around the embankment of the right abutment.

A review of the construction data available indicates that the dam and appurtenant structures were constructed according to the plans and specifications.

c. Operating Records. There are no operating records available.

d. Post-Construction Changes. There is no record of post-construction changes.

e. Seismic Stability. The dam is located in Seismic Zone 2 and in accordance with the recommended Phase I guidelines does not warrant seismic analysis.

SECTION 7  
ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. The visual inspection of Baker Floodwater Reservoir Site 11 indicates the dam is in good condition. The inspection revealed the following:

- (1) Staining of concrete on the riser structure.
- (2) A fallen tree across the channel downstream of the dam.
- (3) Log debris along the shoreline of the reservoir.
- (4) Logs and fallen trees at the downstream end of the emergency spillway.

The hydraulic analysis reveals that the spillways can pass the routed test flood without overtopping the dam.

b. Adequacy of Information. A complete set of design and construction data did allow for a definitive review with the confines of this Phase I - Inspection Report. Therefore, and Adequacy of this dam is based on the design and construction data reviewed, visual inspection, past performance history and sound engineering judgement.

c. Urgency. This dam is in generally good condition. The remedial measures described in Section 7.3 should be accomplished within two years after receipt of this Phase I Inspection Report.

d. Necessity of Additional Investigation. No additional investigation is needed to complete the Phase I inspection.

7.2 Recommendations

There are no recommendations resulting from the Phase I Inspection.

7.3 Remedial Measures

(a) Devise a warning system to follow in the event of emergency conditions.

(b) Remove the fallen tree from the downstream channel, and downstream of the emergency spillway.

(c) Remove fallen trees and logs, that may clog the trash racks, from the reservoir shorelines.

(d) Establish a system such that the reservoir level can be monitored during periods of intense rainfall.



(e) The periodic inspection should be continued on a biennial basis.

#### 7.4 Alternatives

There are no practical alternatives to the remedial measures described in Section 7.3.

APPENDIX A  
INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST  
PARTY ORGANIZATION

A-1

PROJECT SITE 11, BAKER DAM

DATE May 17, 1979

TIME 11:00 AM

WEATHER Fair

W.S. ELEV. 667.3 U.S. - DN.S

PARTY:

1. <u>G. Slaney</u>	<u>HNTB</u>	6. <u></u>
2. <u>S. Mazur</u>	<u>HNTB</u>	7. <u></u>
3. <u>D. LaGatta</u>	<u>GEI</u>	8. <u></u>
4. <u>C. Osgood</u>	<u>GEI</u>	9. <u></u>
5. <u></u>		10. <u></u>

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Dam</u>	<u>D. LaGatta, C. Osgood</u>	
2. <u>Spillway, Outlet Works</u>	<u>S. Mazur</u>	
3. <u>and Downstream Channel</u>	<u>G. Slaney</u>	
4. <u></u>		
5. <u></u>		
6. <u></u>		
7. <u></u>		
8. <u></u>		
9. <u></u>		
10. <u></u>		

## PERIODIC INSPECTION CHECK LIST

A-2

PROJECT BAKER SITE NO 11 DAM DATE May 17, 1979  
PROJECT FEATURE \_\_\_\_\_ NAME \_\_\_\_\_  
DISCIPLINE \_\_\_\_\_ NAME \_\_\_\_\_

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	683.5
Current Pool Elevation	667.3
Maximum Impoundment to Date	675.4 estimated from debris level
Surface Cracks	None observed
Pavement Condition	No pavement, grass cover good
Movement or Settlement of Crest	None apparent
Lateral Movement	None apparent
Vertical Alignment	No misalignment observed
Horizontal Alignment	No misalignment observed
Condition at Abutment and at Concrete Structures	Good condition
Indications of Movement of Structural Items on Slopes	No structural items on slopes
Trespassing on Slopes	No damage due to trespass on slopes
Sloughing or Erosion of Slopes or Abutments	None observed
Rock Slope Protection - Riprap Failures	None observed
Unusual Movement or Cracking at or near Toes	None observed
Unusual Embankment or Downstream Seepage	None observed
Piping or Boils	None observed
Foundation Drainage Features	12" drains clear, small amount of water exiting from left drain
Toe Drains	Brush beginning to grow on riprap gutter
Instrumentation System	None
Vegetation	Grass cover

## PERIODIC INSPECTION CHECK LIST

A-3

PROJECT SITE 11, BAKER DAMDATE May 17, 1979PROJECT FEATURE Intake Channel/StructureNAME D. LaGatta, C. OsgoodDISCIPLINE Geotechnical/StructuralNAME S. Mazur

AREA EVALUATED	CONDITION
<p><u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u></p> <p>a. Approach Channel</p> <p>Slope Conditions</p> <p>Bottom Conditions</p> <p>Rock Slides or Falls</p> <p>Log Boom</p> <p>Debris</p> <p>Condition of Concrete Lining</p> <p>Drains or Weep Holes</p> <p>b. Intake Structure</p> <p>Condition of Concrete</p> <p>Stop Logs and Slots</p>	<p>No approach channel visible but rip-rap for 12' on reservoir slope adjacent to intake structure.</p> <p>None</p> <p>None</p> <p>Galvanized trash rack and concrete surface of riser structure at high and low stages of inlet are in good condition. Bottom water release structure was under water.</p>

## PERIODIC INSPECTION CHECK LIST

A-4

PROJECT SITE 11, BAKER DAMDATE May 17, 1979PROJECT FEATURE Control TowerNAME G. SlaneyDISCIPLINE Structural/Hydraulic EngineersNAME S. Mazur

## AREA EVALUATED

## CONDITION

OUTLET WORKS - CONTROL TOWER

## a. Concrete and Structural

General Condition

Condition of Joints

Spalling

Visible Reinforcing

Rusting or Staining of Concrete

Any Seepage or Efflorescence

Joint Alignment

Unusual Seepage or Leaks in Gate  
Chamber

Cracks

Rusting or Corrosion of Steel

Bottom water release structure (outlet works) consists of inlet structure and 12" I.D. cast iron pipe extended to riser structure. Outlet works structure and control gate were under water.

## b. Mechanical and Electrical

Air Vents

Float Wells

Crane Hoist

Elevator

Hydraulic System

Service Gates

Emergency Gates

Lightning Protection System

Emergency Power System

Wiring and Lighting System

Mechanically operated gate and control mechanism are housed in concrete riser tower structure. Gate is operated from roof of riser structure. Gate and control mechanism appear to be in good operational condition.

## PERIODIC INSPECTION CHECK LIST

A-5

PROJECT SITE 11, BAKER DAMDATE May 16, 1979PROJECT FEATURE Spillway/Outlet Works ConduitNAME G. SlaneyDISCIPLINE Structural/Hydraulic Engs.NAME S. Mazur

## AREA EVALUATED

## CONDITION

OUTLET WORKS - TRANSITION AND CONDUIT

General Condition of Concrete

Rust or Staining on Concrete

Spalling

Erosion or Cavitation

Cracking

Alignment of Monoliths

Alignment of Joints

Numbering of Monoliths

At the time of inspection outlet works conduits were under water. Riser discharge channel consists of 30" I.D. reinforced concrete pipe which is placed on concrete bedding. Discharge conduit appears to be in good condition.

## PERIODIC INSPECTION CHECK LIST

A-6

PROJECT SITE 11, BAKER DAMDATE May 16, 1979PROJECT FEATURE Outlet Structure/ChannelNAME D. LaGatta, C. OsgoodDISCIPLINE Structural/Hydraulic/GeotechnicalNAME S. Mazur, G. Slaney

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - OUTLET STRUCTURE AND OUTLET CHANNEL</u>	
General Condition of Concrete	Concrete outlet works pipe and concrete support bedding are in good condition. Some water staining.
Rust or Staining	
Spalling	None
Erosion or Cavitation	None
Visible Reinforcing	None
Any Seepage or Efflorescence	None
Condition at Joints	Good
Drain Holes	None
Channel	Rocky streambed
Loose Rock or Trees Overhanging Channel	Stream enters woods 50' from discharge pipe
Condition of Discharge Channel	unobstructed



## PERIODIC INSPECTION CHECK LIST

PROJECT SITE 11, BAKER DAMDATE May 16, 1979PROJECT FEATURE Outlet Works/SpillwayNAME D. LaGatta, C. OsgoodDISCIPLINE Structural/Hydraulic/GeotechnicalNAME S. Mazur, G. Slaney

## AREA EVALUATED

## CONDITION

OUTLET WORKS - SPILLWAY WEIR, APPROACH  
AND DISCHARGE CHANNELS

## a. Approach Channel

Good condition

General Condition

None

Loose Rock Overhanging Channel

None

Trees Overhanging Channel

Grass cover with bedrock outcrops and  
wet areas along central floor.

Floor of Approach Channel

## b. Weir and Training Walls

This facility has two spillway structures  
concrete riser with two inlets and aux-  
iliary earth spillway located at right  
abutment. Both spillways are in good  
condition.

General Condition of Concrete

Water Staining

Rust or Staining

Spalling

Some surface scaling

Any Visible Reinforcing

None

Any Seepage or Efflorescence

None

Drain Holes

None

## c. Discharge Channel

General ~~Channel~~ Condition

Good

Loose Rock Overhanging Channel

None

Trees Overhanging Channel

None

Floor of Channel

Grass covered-some wet area channel ends  
abruptly at edge of 2nd growth woods

Other Obstructions

## PERIODIC INSPECTION CHECK LIST

A-8

PROJECT SITE 11, BAKER DAMDATE May 16, 1979PROJECT FEATURE Service Bridge

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

## AREA EVALUATED

## CONDITION

OUTLET WORKS - SERVICE BRIDGE

## a. Super Structure

This facility has no service bridge.

Bearings

Anchor Bolts

Bridge Seat

Longitudinal Members

Under Side of Deck

Secondary Bracing

Deck

Drainage System

Railings

Expansion Joints

Paint

## b. Abutment &amp; Piers

General Condition of Concrete

Alignment of Abutment

Approach to Bridge

Condition of Seat &amp; Backwall

Reproduced from  
best available copy.

RISER

Caution Be extremely careful when using ladders. Check condition before using. Ladders are sometimes broken, loose, corroded, and or slippery.  
Use safety harness.

adders:  
inside and out

Condition of protective coating\_\_\_;  
Corrosion\_\_\_; Damaged parts\_\_\_; Loose\_\_\_;  
Other\_\_\_.

oncrete:  
inside and out

Cracking\_\_\_; Spalling\_\_\_; Other deterioration  
2; Excessive movement (check joint at riser  
and conduit)\_\_\_; Other\_\_\_.

rashracks:  
low and high stage

Condition of protective coatings\_\_\_; Corrosion  
\_\_\_; Damaged parts\_\_\_; Condition of fastenings  
\_\_\_; Need of gratings due to beaver\_\_\_; Safety  
condition (protruding fastenings, sharp edges,  
etc.)\_\_\_; Other\_\_\_.

anhole:

Condition of protective coatings\_\_\_; Corrosion  
\_\_\_; Damage\_\_\_; Lock operable\_\_\_; Other\_\_\_.

ate:  
including lifting  
device, stem, guides,  
disc

Condition of protective coating\_\_\_; Corrosion  
\_\_\_; Damaged parts\_\_\_; Condition of fasten-  
ings\_\_\_; Stem alignment\_\_\_; Lubrication\_\_\_;  
Operation\_\_\_; Other\_\_\_.

afety Items:

Condition of warning signs\_\_\_; Condition of  
safety equipment\_\_\_; Other\_\_\_.

ONMENTS WRR PERSONNEL WILL CHECK RISER &  
APPURTENANCES AT LATER DATE. SALL RWS  
COAT SCALING OFF IN ONE SPOT

VEGETATION

	Dam	Emergency Spillways		1/ Dike	Outlet Channel	Water way	Other ( )
Condition of stand (including need for lime and fertilizer)	<u>1</u>	—	<u>1</u>	—	<u>NA</u>	—	—
Undesirable vegetation	<u>3</u>	—	<u>2</u>	—	<u>1</u>	—	—
Drainage (surface)	<u>NA</u>	—	<u>2</u>	—	<u>NA</u>	—	—
Erosion 2/	<u>1</u>	—	<u>1</u>	—	<u>1</u>	—	—
Sedimentation	<u>1</u>	—	<u>1</u>	—	<u>1</u>	—	—
Condition of planting	<u>NA</u>	—	—	—	—	—	—
Pest control	—	—	—	—	—	—	—
Fire control	—	—	—	—	—	—	—

COMMENTS BUSHES AROUND OUTLET PIPE SHOULD BE  
REMOVED

EMBANKMENT, STRUCTURAL, & OTHER DRAINS

		Dam		1/ ( )	Other ( )
Depth of Flow	With any obstruction	—	—	—	—
(in inches above invert)	Without any obstruction	<u>0</u>	<u>0</u>	—	—
Turbidity of Discharge	With any obstruction	—	—	—	—
(yes, no)	Without any obstruction	<u>NA</u>	<u>NA</u>	—	—
Condition of Protective	Outside	<u>1</u>	<u>1</u>	—	—
Coating	Inside	<u>1</u>	<u>1</u>	—	—
Obstruction in Flow		<u>NA</u>	<u>NA</u>	—	—
(yes, no)					
Animal Guard Condition		<u>1</u>	<u>1</u>	—	—
Outlet Condition		<u>1</u>	<u>1</u>	—	—
Retarding Pool Elevation (ft. msl)	_____ or _____ (ft.)	above below _____			
Other	_____				

COMMENTS \_\_\_\_\_

king downstream.  
cluding wave, surface, stream, manmade, and livestock erosion.

EMBANKMENT AND EXCAVATED SLOPES

(Report riprap and vegetation and erosion condition under Items 4 and 5.)

	Dam	Dike	Emergency Spillways <sup>1/</sup>		Other	
			left	right	( )	( )
Sliding or sloughing	<u>1</u>	—	—	—	—	—
Holes (rodent and other)	<u>1</u>	—	—	—	—	—
(check especially at embankments)						
Excessive settlement (embankments)	<u>1</u>	—	—	—	—	—
Cracks						
Traverse	<u>1</u>	—	—	—	—	—
Longitudinal	<u>1</u>	—	—	—	—	—
Seepage <sup>2/</sup>	<u>1</u>	—	—	—	—	—
Piping <sup>2/</sup>	<u>1</u>	—	—	—	—	—

COMMENTS \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

RIPRAP

	Displ. of Rock	Loss of Spalls	Loss of Bedding	Erosion of Found.	Break- down of Rock
Dam					
Upstream berm	—	—	—	—	—
Principal Spillway Outlet	—	—	—	—	—
Embankment Outlets					
left <i>DOWNSTREAM</i>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
right <i>DOWNSTREAM</i>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Emergency Spillway					
location _____	—	—	—	—	—
location _____	—	—	—	—	—
Waterways					
location _____	—	—	—	—	—
location _____	—	—	—	—	—
Outlet Channel	<u>3</u>	<u>3</u>	<u>1</u>	<u>1</u>	<u>1</u>
Other _____	—	—	—	—	—

COMMENTS RIPRAP AT OUTLET END OF PLUNGE POOL

NEEDS REPAIR

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

looking downstream.

check especially at downstream face of embankments.

EMBANKMENT AND EXCAVATED SLOPES

(Report riprap and vegetation and erosion condition under Items 4 and 5.)

	Dam	Dike	Emergency Spillways		Other	
			left	right <sup>1/</sup>	( )	( )
Sliding or sloughing	<u>1</u>	—	—	—	—	—
Holes (rodent and other) (check especially at embankments)	<u>1</u>	—	—	—	—	—
Excessive settlement (embankments)	<u>1</u>	—	—	—	—	—
Cracks						
Traverse	<u>1</u>	—	—	—	—	—
Longitudinal	<u>1</u>	—	—	—	—	—
Seepage <u>2/</u>	<u>1</u>	—	—	—	—	—
Piping <u>2/</u>	<u>1</u>	—	—	—	—	—

COMMENTS \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

RIPRAP

	Displ. of Rock	Loss of Spalls	Loss of Bedding	Erosion of Found.	Break- down of Rock
Dam					
Upstream berm	—	—	—	—	—
Principal Spillway Outlet	—	—	—	—	—
Embankment Gutters					
left <u>DWNSTM</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
right <u>DWNSTM</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Emergency Spillway					
location _____	—	—	—	—	—
location _____	—	—	—	—	—
Waterways					
location _____	—	—	—	—	—
location _____	—	—	—	—	—
Outlet Channel	<u>3</u>	<u>3</u>	<u>1</u>	<u>1</u>	<u>1</u>
Other _____	—	—	—	—	—

COMMENTS RIPRAP AT OUTLET END OF PLUNGE POOL

NEEDS REPAIR

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Looking downstream.  
Check especially at downstream face of embankments.

but I have not been able to find any other examples.

Except where otherwise indicated, completion of this form may be facilitated by ranking maintenance items on a 1 to 4 basis where

- 1 = satisfactory  
2 = satisfactory, but check carefully at next inspection  
3 = requires maintenance this season  
4 = requires immediate attention.

WATERSHED BAKER RIVER SITE 11 DATE 5-20-77  
 INSPECTED BY KEAR GINNENY LUNTLA  
MULLIGAN FRISER MACPHERSON

[illegible]

COMMENTS OLD WHEEL RUTS IN LEVEL SECTION OF  
EM. SPILLWAY

Timber stand at reservoir.	.	.	.	.	.	.	.	.	<u>2</u>
Debris and slash.	.	.	.	.	.	.	.	.	<u>2</u>
Sediment level in relation to low stage inlet	.	.	.	.	.	.	.	.	

COMMENTS BLOOD DROPS AROUND EDGE OF PERMANENT  
POOL.



(specify) \_\_\_\_\_

**Concrete:**  
inside and out

Cracking\_\_\_; Spalling\_\_\_; Other deterioration  
\_\_\_; Excessive movement (check joints)\_\_\_;  
Waterstops ; Joint sealant\_\_\_; Other .

Trashracks:  
low and high stage

Condition of protective coatings\_\_\_; Corrosion\_\_\_; Damaged parts\_\_\_; Condition of fastenings\_\_\_; Need of gratings due to beaver\_\_\_; Safety condition (protruding fastenings, sharp edges, etc.) ; Other .

Gates:  
including lifting  
device, stem, guides,  
disc, flap

Condition of protective coating\_\_\_; Corrosion\_\_\_; Damaged parts\_\_\_; Condition of fastenings\_\_\_; Stem alignment\_\_\_; Operation\_\_\_; Lubrication ; Wood decay ; Other\_\_\_\_\_.

### Structure Drainage:

Report under "Embankment and Other Drains"

Structure, Railing,  
Grates, Barriers,  
etc.

Condition of protective coating\_\_\_; Corrosion\_\_\_; Damaged parts\_\_\_; Condition of Fastenings\_\_\_; Wood decay\_\_\_; Safety condition (protruding fastenings, sharp edges, etc.)  
; Other .

**Safety Items:**

Condition of warning signs\_\_\_; Condition of  
safety equipment ; Other .

## COMMENTS

CHANNEL

Stream obstructions.	.	.	.	.	.	.	.	.	.	.	.	<u>1</u>
Debris in stream.	.	.	.	.	.	.	.	.	.	.	.	<u>1</u>
Sediment bars controlled.	.	.	.	.	.	.	.	.	.	.	.	<u>1</u>
Plunge pool stability.	.	.	.	.	.	.	.	.	.	.	.	<u>1</u>
Fish habitat appurtenances	.	.	.	.	.	.	.	.	.	.	.	<u>NA</u>
Riprap -- Report under "Riprap" (item 4)												

## COMMENTS

7. RISER

Caution Be extremely careful when using ladders. Check condition before using. Ladders are sometimes broken, loose, corroded, and or slippery. Use safety harness.

Ladders:  
inside and out

Condition of protective coating\_\_\_;  
Corrosion\_\_\_; Damaged parts\_\_\_; Loose\_\_\_;  
Other\_\_\_.

Concrete:  
inside and out

Cracking 1; Spalling 1; Other deterioration 1; Excessive movement (check joint at riser and conduit)\_\_\_; Other\_\_\_.

Trashracks:  
low and high stage

Condition of protective coatings\_\_\_; Corrosion 1; Damaged parts 1; Condition of fastenings 1; Need of gratings due to beaver\_\_\_; Safety condition (protruding fastenings, sharp edges, etc.)\_\_\_; Other\_\_\_.

Manhole:

Condition of protective coatings\_\_\_; Corrosion \_\_\_; Damage\_\_\_; Lock operable\_\_\_; Other\_\_\_.

Gate:  
including lifting device, stem, guides, disc

Condition of protective coating\_\_\_; Corrosion \_\_\_; Damaged parts\_\_\_; Condition of fastenings\_\_\_; Stem alignment\_\_\_; Lubrication\_\_\_; Operation\_\_\_; Other\_\_\_.

Safety Items:

Condition of warning signs\_\_\_; Condition of safety equipment\_\_\_; Other\_\_\_.

COMMENTS Did not go down riser. Suggest interior of riser and gate operation be checked at suitable intervals.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

# 4. VEGETATION

	Dam	Emergency Spillways <sup>1/</sup>		Dike	Outlet Channel	Water way	Other ( )
		left	right				
Condition of stand (including need for lime and fertilizer)	—	1	1	—	—	—	—
Undesirable vegetation	—	—	—	—	—	—	—
Drainage (surface)	—	—	—	—	—	—	—
Erosion <sup>2/</sup>	—	—	—	—	—	—	—
Sedimentation	—	—	—	—	—	—	—
Condition of planting	—	—	—	—	—	—	—
Pest control	—	—	—	—	—	—	—
Fire control	—	—	—	—	—	—	—

COMMENTS Some small brush on downstream side of dam. Generally looks  
good. Emergency spillway - wet, reverting to aquatic vegetation.

# 5. EMBANKMENT, STRUCTURAL, & OTHER DRAINS

		Dam <sup>1/</sup>		Other	
		left	right	( )	( )
Depth of Flow (in inches above invert)	With any obstruction	<u>1"</u>	<u>none</u>	—	—
	Without any obstruction	—	—	—	—
Turbidity of Discharge (yes, no)	With any obstruction	—	—	—	—
	Without any obstruction	<u>no</u>	<u>no</u>	—	—
Condition of Protective Coating	Outside	<u>1</u>	<u>1</u>	—	—
	Inside	<u>1</u>	<u>1</u>	—	—
Obstruction in Flow (yes, no)		<u>no</u>	<u>no</u>	—	—
Animal Guard Condition		<u>1</u>	<u>1</u>	—	—
Outlet Condition		<u>1</u>	<u>1</u>	—	—
Retarding Pool Elevation (ft. msl) _____ or <u>≈ 4 in. (ftx)</u> <sup>above</sup>				<u>below</u>	<u>L.S.</u>
Other _____					

COMMENTS \_\_\_\_\_

<sup>1/</sup>Looking downstream.

<sup>2/</sup>Including wave, surface, stream, manmade, and livestock erosion.

### 3. EMBANKMENT AND EXCAVATED SLOPES

(Report riprap and vegetation and erosion condition under Items 4 and 5.)

	Dam	Dike	Emergency Spillways <sup>1/</sup>		Other	
			left	right	( )	( )
Sliding or sloughing	<u>1</u>	—	—	<u>1</u>	—	—
Holes (rodent and other) (check especially at embankments)	<u>1</u>	—	—	<u>1</u>	—	—
Excessive settlement (embankments)	<u>1</u>	—	—	—	—	—
Cracks						
Traverse	<u>1</u>	—	—	<u>1</u>	—	—
Longitudinal	<u>1</u>	—	—	<u>1</u>	—	—
Seepage <u>2/</u>	<u>1</u>	—	—	<u>1</u>	—	—
Piping <u>2/</u>	<u>1</u>	—	—	<u>1</u>	—	—

COMMENTS

### 4. RIPRAP

	Displ. of Rock	Loss of Spalls	Loss of Bedding	Erosion of Found.	Break- down of Rock
Dam					
Upstream berm	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Principal Spillway Outlet	<u>3</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Embankment Gutters					
left downstream	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
right downstream	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Emergency Spillway					
location	—	—	—	—	—
location	—	—	—	—	—
Waterways					
location	—	—	—	—	—
location	—	—	—	—	—
Outlet Channel	—	—	—	—	—
Other	—	—	—	—	—

COMMENTS Two or three pieces of riprap at downstream outlet of plunge pool should be removed.

Looking downstream.  
Check especially at downstream face of embankments.

# MAINTENANCE CHECKLIST FOR PL 566 FLOOD CONTROL STRUCTURES

This maintenance checklist is a guide for determining the maintenance required for Public Law 566 flood control structures in New Hampshire. It doesn't take the place of experience and judgment and is not inclusive. Items of a difficult nature to check, such as principal spillway conduit condition, are not included. Intensive checks of these items are necessary at proper intervals. Review of As Built drawings, the design folder, structure history, and previous maintenance reports should be part of the inspection. Prompt maintenance is a vital part of safe and effective operation.

Except where otherwise indicated, completion of this form may be facilitated by ranking maintenance items on a 1 to 4 basis where

- 1 = satisfactory  
2 = satisfactory, but check carefully at next inspection  
3 = requires maintenance this season  
4 = requires immediate attention.

WATERSHED Baker SITE 11 DATE 6-13-78  
INSPECTED BY Garv Kerr, Lvall Milligan (WRB); Mike Dannehy, Nick Lubtala, Ray Wenninger  
(SCS)

## 1. GENERAL ITEMS

[illegible]

COMMENTS No trash, looks good.

## 2. RESERVOIR

Timber stand at reservoir.	.	.	.	.	.	.	.	<u>1</u>
Debris and slash.	.	.	.	.	.	.	.	<u>1</u>
Sediment level in relation to low stage inlet	.	.	.	.	.	.	.	<u>1</u>

## COMMENTS

PAST INSPECTION REPORTS

### AVAILABLE ENGINEERING DATA

1. A set of drawings (24 sheets), dated November 1970, showing plans and details of the dam and appurtenant structures.
2. Design Data: including layout, hydraulic design, geology and soils reports, structural design, quantities and specifications.
3. Construction Data: including as-built plans, job diaries, surveying records, test drilling logs, compaction test results, concrete tests, and certificate of completion.

All of the above are on file with the U.S.D.A. Soil Conservation Service, Federal Building, Durham, N.H. 03824.

APPENDIX B  
ENGINEERING DATA

1. LIST OF DESIGN, CONSTRUCTION AND MAINTENANCE RECORDS
2. PAST INSPECTION REPORTS
3. PLAN AND DETAILS







FIG 1

REAM LIMIT OF GRADING  
RGENCY SPILLWAY




NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
SITE NO. 11	
BAKER FLOODWATER RESERVOIR	
TRIBUTARY TO BAKER RIVER	WENTWORTH, N.H.

Figure 1 of 2


2af2



1 of 2



SECTION A-A



SECTION C-C

1. THE INFORMATION SHOWN ON THESE DRAWINGS IS BASED ON THE ORIGINAL CONSTRUCTION PLANS AND VISUAL OBSERVATIONS MADE DURING THE FIELD INSPECTION. DIMENSIONS OR MATERIALS INDICATED ON THESE DRAWINGS WHICH WERE BELOW GRADE OR WATER DURING THE TIME OF INSPECTION WERE NOT VERIFIED.

2. THE ELEVATIONS SHOWN ARE 1929 MSL DATUM.

EARTH FILL REQUIREMENTS	
MAXIMUM WATER CONTENT	25.0%
MINIMUM PLACED IN PLACE	95.0%
MAXIMUM PERCENTAGE OF MATERIAL PASSING NO. 200 SIEVE	5.0%
MINIMUM PERCENTAGE OF MATERIAL PASSING NO. 40 SIEVE	85.0%
MINIMUM PERCENTAGE OF MATERIAL PASSING NO. 10 SIEVE	95.0%

NATIONAL PROGRAM OF INSPECTION OF DAMS	
SITE NO. II	
BAKER FLOODWATER	
RESERVOIR	
THREATS	WATER QUALITY
BAKER FLOOD	

Figure 2 of 2

2af2

APPENDIX C

PHOTOGRAPHS

FOR LOCATION OF PHOTOS, SEE FIGURE 1  
LOCATED IN APPENDIX B



PHOTO NO. 1 - View of upstream face of dam and a portion of the reservoir from right abutment.



PHOTO NO. 2 - View of upstream face of dam from left abutment.



PHOTO NO. 3 - View of dam crest from left abutment.



PHOTO NO. 4 - View of downstream slope and rip-rap gutter  
looking toward right abutment.






PHOTO NO. 5 - View of riser from dam.




PHOTO NO. 6 - View of high stage trash rack.



PHOTO NO. 7 - View of left side of riser.



PHOTO NO. 8 - Emergency earth spillway looking toward downstream end.



PHOTO NO. 9 - View of upstream end of emergency spillway.




PHOTO NO. 10 - View of wet areas in the emergency spillway,  
located near the axis of the dam.



PHOTO NO. 11 - View of discharge area of emergency spillway.




PHOTO NO. 12 - View of concrete pipe principal spillway outlet and plunge pool.



PHOTO NO. 13 - View of principal spillway outlet and portion of plunge pool.



PHOTO NO. 14 - View of outlet works and downstream face of dam.

PHOTO NO. 15 - View of outlet works and  
downstream channel.





U.S. DEPARTMENT OF AGRICULTURE  
 Natural Resources Administration

U.S. DEPARTMENT OF AGRICULTURE  
 SOIL CONSERVATION SERVICE

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

DATE	NAME	ADDRESS	CITY	STATE	ZIP	PHONE	TELETYPE	TELEFAX
10/1/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/2/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/3/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/4/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/5/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/6/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/7/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/8/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/9/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/10/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/11/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/12/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/13/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/14/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/15/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/16/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/17/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/18/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/19/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/20/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/21/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/22/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/23/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/24/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/25/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/26/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/27/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/28/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/29/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/30/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		
10/31/54	W. H. HARRIS	1000 1/2 N. 1st St.	St. Paul	MN	55101	232-1234		

Reproduced from  
 last available copy



44-657

1877-1878

Work . . . Design Comparison

Emergency Spending

1. Shirley M. Puckett 1900-1901

*Handwritten signature*

1894-1895

Country - England      Plot in East Slope

241120, 2004

100

---

100

1. *What is the purpose of the study?*  
 2. *What are the research questions or hypotheses?*  
 3. *What is the study design?*  
 4. *What are the variables?*  
 5. *What are the data sources?*  
 6. *What are the data collection methods?*  
 7. *What are the data analysis methods?*  
 8. *What are the results?*  
 9. *What are the conclusions?*  
 10. *What are the limitations?*  
 11. *What are the implications?*  
 12. *What are the future research directions?*

1. *Phragmites australis* (Cav.) Trin. ex Steud.  
 2. *Scirpus americanus* (L.) Link.  
 3. *Scirpus setaceus* (L.) Link.  
 4. *Scirpus robustus* (L.) Link.  
 5. *Scirpus tabernaemontani* (Cav.) Trin. ex Steud.  
 6. *Scirpus torreyana* (L.) Link.  
 7. *Scirpus yagara* (L.) Link.  
 8. *Scirpus yagara* (L.) Link.  
 9. *Scirpus yagara* (L.) Link.  
 10. *Scirpus yagara* (L.) Link.  
 11. *Scirpus yagara* (L.) Link.  
 12. *Scirpus yagara* (L.) Link.  
 13. *Scirpus yagara* (L.) Link.  
 14. *Scirpus yagara* (L.) Link.  
 15. *Scirpus yagara* (L.) Link.  
 16. *Scirpus yagara* (L.) Link.  
 17. *Scirpus yagara* (L.) Link.  
 18. *Scirpus yagara* (L.) Link.  
 19. *Scirpus yagara* (L.) Link.  
 20. *Scirpus yagara* (L.) Link.  
 21. *Scirpus yagara* (L.) Link.  
 22. *Scirpus yagara* (L.) Link.  
 23. *Scirpus yagara* (L.) Link.  
 24. *Scirpus yagara* (L.) Link.  
 25. *Scirpus yagara* (L.) Link.  
 26. *Scirpus yagara* (L.) Link.  
 27. *Scirpus yagara* (L.) Link.  
 28. *Scirpus yagara* (L.) Link.  
 29. *Scirpus yagara* (L.) Link.  
 30. *Scirpus yagara* (L.) Link.  
 31. *Scirpus yagara* (L.) Link.  
 32. *Scirpus yagara* (L.) Link.  
 33. *Scirpus yagara* (L.) Link.  
 34. *Scirpus yagara* (L.) Link.  
 35. *Scirpus yagara* (L.) Link.  
 36. *Scirpus yagara* (L.) Link.  
 37. *Scirpus yagara* (L.) Link.  
 38. *Scirpus yagara* (L.) Link.  
 39. *Scirpus yagara* (L.) Link.  
 40. *Scirpus yagara* (L.) Link.  
 41. *Scirpus yagara* (L.) Link.  
 42. *Scirpus yagara* (L.) Link.  
 43. *Scirpus yagara* (L.) Link.  
 44. *Scirpus yagara* (L.) Link.  
 45. *Scirpus yagara* (L.) Link.  
 46. *Scirpus yagara* (L.) Link.  
 47. *Scirpus yagara* (L.) Link.  
 48. *Scirpus yagara* (L.) Link.  
 49. *Scirpus yagara* (L.) Link.  
 50. *Scirpus yagara* (L.) Link.  
 51. *Scirpus yagara* (L.) Link.  
 52. *Scirpus yagara* (L.) Link.  
 53. *Scirpus yagara* (L.) Link.  
 54. *Scirpus yagara* (L.) Link.  
 55. *Scirpus yagara* (L.) Link.  
 56. *Scirpus yagara* (L.) Link.  
 57. *Scirpus yagara* (L.) Link.  
 58. *Scirpus yagara* (L.) Link.  
 59. *Scirpus yagara* (L.) Link.  
 60. *Scirpus yagara* (L.) Link.  
 61. *Scirpus yagara* (L.) Link.  
 62. *Scirpus yagara* (L.) Link.  
 63. *Scirpus yagara* (L.) Link.  
 64. *Scirpus yagara* (L.) Link.  
 65. *Scirpus yagara* (L.) Link.  
 66. *Scirpus yagara* (L.) Link.  
 67. *Scirpus yagara* (L.) Link.  
 68. *Scirpus yagara* (L.) Link.  
 69. *Scirpus yagara* (L.) Link.  
 70. *Scirpus yagara* (L.) Link.  
 71. *Scirpus yagara* (L.) Link.  
 72. *Scirpus yagara* (L.) Link.  
 73. *Scirpus yagara* (L.) Link.  
 74. *Scirpus yagara* (L.) Link.  
 75. *Scirpus yagara* (L.) Link.  
 76. *Scirpus yagara* (L.) Link.  
 77. *Scirpus yagara* (L.) Link.  
 78. *Scirpus yagara* (L.) Link.  
 79. *Scirpus yagara* (L.) Link.  
 80. *Scirpus yagara* (L.) Link.  
 81. *Scirpus yagara* (L.) Link.  
 82. *Scirpus yagara* (L.) Link.  
 83. *Scirpus yagara* (L.) Link.  
 84. *Scirpus yagara* (L.) Link.  
 85. *Scirpus yagara* (L.) Link.  
 86. *Scirpus yagara* (L.) Link.  
 87. *Scirpus yagara* (L.) Link.  
 88. *Scirpus yagara* (L.) Link.  
 89. *Scirpus yagara* (L.) Link.  
 90. *Scirpus yagara* (L.) Link.  
 91. *Scirpus yagara* (L.) Link.  
 92. *Scirpus yagara* (L.) Link.  
 93. *Scirpus yagara* (L.) Link.  
 94. *Scirpus yagara* (L.) Link.  
 95. *Scirpus yagara* (L.) Link.  
 96. *Scirpus yagara* (L.) Link.  
 97. *Scirpus yagara* (L.) Link.  
 98. *Scirpus yagara* (L.) Link.  
 99. *Scirpus yagara* (L.) Link.  
 100. *Scirpus yagara* (L.) Link.

1

\_\_\_\_\_




Figure 1

Baker #11

Step 4 Reach Outflow  $L_T = 2500 \text{ ft}$

$$Q_{P_1} = 32,700 \text{ cfs}$$

$$\text{Stage}_1 = 17.1 \text{ ft} \quad \text{area}_1 = 1914 \text{ ft}^2$$

$$V_1 = \frac{1914 \times 1200}{43560} = 52.7 \approx \frac{125}{2}$$

Reach OK

$$Q_{P_2 \text{ Trial}} = 32700 \left(1 - \frac{57.2}{125}\right) = 18,900 \text{ cfs}$$

$$\text{Stage}_2 = 13.9 \text{ ft} \quad \text{area}_2 = 1210 \text{ ft}^2$$

$$V_2 = \frac{1210 \times 1200}{43560} = 33.3 \text{ sec ft}$$

$$V_{\text{ave}} = \frac{33.3 + 57.2}{2} = 45.3 \text{ sec ft}$$

$$Q_{P_2} = 32700 \left(1 - \frac{45.3}{125}\right) = 23,860 \text{ cfs}$$

End partial Reach 1  $L = 1500 \text{ ft}$   $Q = 23,860 \text{ cfs}$

$$\text{Stage}_1 = 14.4 \text{ ft} \quad \text{area}_1 = 1310 \text{ ft}^2$$

$$V_1 = \frac{1310 (1300)}{43560} = 39.1 \text{ sec ft}$$

$$Q_{P_2 \text{ Trial}} = 23860 \left(1 - \frac{39.1}{125}\right) = 14,300 \text{ cfs}$$

$$\text{Stage}_2 = 12.5 \text{ ft} \quad \text{area}_2 = 954 \text{ ft}^2$$

$$V_2 = \frac{954 \times 1300}{43560} = 28.5 \text{ sec ft}$$

$$V_{\text{ave}} = \frac{28.5 + 39.1}{2} = 33.8 \text{ sec ft}$$

$$Q_{P_2} = 23,860 \left(1 - \frac{33.8}{125}\right) = 15,200 \text{ cfs}$$

$$\text{Stage}_2 = 12.8 \text{ ft}$$

<b>HNTB</b> HOWARD NEEDLES TAMMEN & BERGENDOFF	Made by <u>RY</u>	Date <u>5/25/77</u>	Job No <u>5765-11-07</u>
	Checked by <u>HK</u>	Date <u>5/25/77</u>	Sheet No <u>5</u>
For <u>Biker # 11</u>			

## Estimate of Downstream Damage

### Step 1 Reservoir Storage

Ht top dam elevation 673.5 feet  
Storage 112 acre-ft

### Step 2 Breach Outflow

$$Q_{\text{breach}} = 8/27 \sqrt{g} W_0 Y_0^{3/2}$$

$W_0 = 40\%$  of dam length of 681 feet

$Y_0 = \text{Height-streambed to top of dam} = 24 \text{ ft}$

Stream bed very small portion of valley section  
csc 17 ft for  $Y_0 = \text{height - valley to top of dam}$

$$Q_{\text{breach}} = 8/27 \sqrt{g} (40)(681)(24)^{3/2} = 32,700 \text{ cfs}$$

Spillway discharge 600 cfs

Total Discharge 32,700 cfs

### Step 3 Stage Discharge

T.W. = 20'

$n = .04$


$n = .08$

Breach length = 2500'

Channel S = .0321

$n_{\text{ch}} = .04$

$n_{\text{OB}} = .08$



Stage      Discharge

3 ft      1450 cfs


7      3200

9      6180

12      12,970

15      23,250

18 ft      37,600



3244-11  
 515-11-07  
 Kennedy's knowledge  
 discharge curve  
 to 11.5 515-11-07  
 515 cc/sec. curve  
 extrapolated above  
 to 11.5 515-11-07


705

515 cc/sec. curve

10.5

13.5





<b>HNTB</b> HOWARD NEEDLES TAMMEN & BERGENDOFF	Made by <u>RY</u>	Date <u>6/20/79</u>	Job No <u>5765-11-07</u>
	Checked by <u>H.M.</u>	Date <u>7-1-79</u>	Sheet No <u>4</u>
For <u>Eaker # 11</u>			

### Step 3 Estimate of Surge - Storage Effect

$$Q_{P1} = 825 \text{ cfs}$$

$$\text{Runoff} = 9.5 \text{ mm.}$$

see page 2

$$Q_{P2} = Q_{P1} \times \left(1 - \frac{\text{stor}}{9.5}\right)$$

$t_r$  in sec - (t read from figure 1 - 8 sec-ft)

$$\text{stor (cu)} = \frac{\text{stor (sec-ft)} \times 12 \text{ in/ft}}{.55 \text{ gpm} \times 640 \text{ sec/1 min}} = .034 (\text{cu})$$

<u> Elev</u>	<u> stor (sec-ft)</u>	<u> stor (cu)</u>	<u> Q<sub>P2</sub></u>
81	89	3.03	562
82	99	3.37	532
83	110	3.74	500
84	117	3.98	479
85	124	4.22	459

See figure 2 for plot and final outflow

From figure 2 Outflow 475 cfs

Stor 683.1

Freeboard 0.4 ft



**HNTB**

HOWARD NEEDLES TAMMEN &amp; BERGENDOFF

Made by

RY

Date

6/20/79

Job No

5965-11-07

Checked by

H/M

Date

7-27-79

Sheet No

3

For

Baker #11

Step 2 Calculation of Test Flood SurgeStage-Discharge Curve

<u>Elev.</u>	<u>ft above</u> <u>Emer. Spillway</u>	<u>A Riser</u> <u>Pipe Flow</u>	<u>B Emer</u> <u>Spillway</u>	<u>C Crest</u> <u>of Dam</u>	<u>Total</u>
620.5	0	77 cfs	0		77 cfs
681		121	27 cfs		123
682		124	131		235
683		126	355		781
685		127	500	0	627
687		158	570*	188 cfs	766

A from Baker River Dam #11, Baker River, S.E. Jackson, Wyo.  
See copies of calcs. at the end of this section.

B. Same as A

\* see Figure 2

C computed as flow over a broad-crested weir

$$Q = CLH^{3/2}$$

$$C = 3.09$$

$$L = 681$$

$$Q = 2104 H^{3/2}$$

See Figure 2 for plot

**HNTB**

HOWARD NEEDLES TAMMEN &amp; BERGENDOFF

Made by

RY

Date

6/20/79

Job No

5765-11-27

Checked by

FM

Date

6/20/79

Sheet No

2

For

Baker #11

Step 1 Calculation of Test Flood Inflow

Classification: Size: Small  
Hazard: Significant

Hydrologic Evaluation Guidelines Recommends

100yr flood to 1/2 PMF for Test Flood

use 1/2 PMF as hazard classification is on higher  
side of significant - dwellings + road affected

See Mountainside Lane PMF = 3000 csm (Maximum value  
recommended)

$$\begin{aligned}\text{Test Flood} &= \frac{1}{2} \times 3000 \text{ csm} \times .55 \text{ to mil} \\ \text{Inflow} &= 725 \text{ cfs}\end{aligned}$$

As there is a flood control structure in the section + can store  
above the normal pool - can we store for duration of  
a portion of the Test Flood Inflow

1.000 ft normal pool  
70000 cu ft at crest of emergency spillway  
82000 cu ft available for TFI storage

$$\begin{aligned}\text{Volume of } 1/2 \text{ PMF} &= 17'12" \times \frac{1}{2} \times 640 \frac{\text{sq ft}}{\text{mi}^2} \times .55 \text{ mi}^2 \\ &= 279100 \text{ cu ft}\end{aligned}$$

<b>HNTB</b> HOWARD NEEDLES TAMMEN & BERGENDOFF For <u>Baker Dam Site #11</u>	Made by <u>RY</u>	Date <u>5/20/79</u>	Job No <u>5765 11-07</u>
	Checked by <u>-1-</u>	Date <u>5-1-</u>	Sheet No <u>1</u>

## Hydraulics and Hydrology

Baker River Dam Site 11 Located on a Tributary to the Baker River in the Town of Wentworth, N. H. in the Merrimack River Basin.

### Classification

Size : Small  
Hazard : Significant

### Basic Data

D.A. = 5.55 sq. mi.  
Upstream Basin Mountains  
700 ft/mile

Reservoir : Recreation Pool = elev. 607.0  
Stor = 1000 ac-ft  
Inlet Spillway just div. 579.5  
Stor = 1000 ac-ft  
Top of Dam elev. 603.5  
Stor 125 ac-ft

### Dam : Earth

Length : 681 ft  
Height : 24 ft

### Spillways

Riser crest 579.12  
Riser length 15 feet  
Emergency Spillway : 600.5 ft  
Width 50 ft.

See Appendix B for plan of dam

APPENDIX D  
HYDROLOGIC AND HYDRAULIC COMPUTATIONS

4/23/70

FREEBOARD RAINFALL 10.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

EMER. SPW. RAINFALL 0.90

CHAS. W. WILSON - OFFICE

4/23/50

4/23/50

TIME	INFLUX	AVE. IN	OUTFLOW	RETRY.
0.05	0.	0.	0.	669.99
0.10	0.	0.	0.	669.99
0.15	0.	0.	0.	669.99
0.20	0.	0.	0.	669.99
0.25	0.	0.	0.	669.99
0.30	0.	0.	0.	669.99
0.35	0.	0.	0.	669.99
0.40	0.	0.	0.	669.99
0.45	0.	0.	0.	669.99
0.50	0.	0.	0.	669.99
0.55	0.	0.	0.	669.99
1.00	0.	0.	0.	669.99
1.05	0.	0.	0.	669.99
1.10	0.	0.	0.	669.99
1.15	0.	0.	0.	669.99
1.20	0.	0.	0.	669.99
1.25	0.	0.	0.	669.99
1.30	0.	0.	0.	669.99
1.35	0.	0.	0.	669.99
1.40	0.	0.	0.	669.99
1.45	0.	0.	0.	669.99
1.50	0.	0.	0.	669.99
1.55	0.	0.	0.	669.99
2.00	0.	0.	0.	669.99
2.05	0.	0.	0.	669.99
2.10	0.	0.	0.	669.99
2.15	0.	0.	0.	669.99
2.20	0.	0.	0.	669.99
2.25	0.	0.	0.	669.99
2.30	0.	0.	0.	669.99
2.35	0.	0.	0.	669.99
2.40	0.	0.	0.	669.99
2.45	0.	0.	0.	669.99
2.50	0.	0.	0.	669.99
2.55	0.	0.	0.	669.99
3.00	0.	0.	0.	669.99
3.05	0.	0.	0.	669.99
3.10	0.	0.	0.	669.99
3.15	0.	0.	0.	669.99
3.20	0.	0.	0.	669.99
3.25	0.	0.	0.	669.99
3.30	0.	0.	0.	669.99
3.35	0.	0.	0.	669.99
3.40	0.	0.	0.	669.99
3.45	0.	0.	0.	669.99
3.50	0.	0.	0.	669.99
3.55	0.	0.	0.	669.99
4.00	0.	0.	0.	669.99
4.05	0.	0.	0.	669.99
4.10	0.	0.	0.	669.99
4.15	0.	0.	0.	669.99
4.20	0.	0.	0.	669.99
4.25	0.	0.	0.	669.99
4.30	0.	0.	0.	669.99
4.35	0.	0.	0.	669.99
4.40	0.	0.	0.	669.99
4.45	0.	0.	0.	669.99
4.50	0.	0.	0.	669.99
4.55	0.	0.	0.	669.99
5.00	0.	0.	0.	669.99
5.05	0.	0.	0.	669.99
5.10	0.	0.	0.	669.99
5.15	0.	0.	0.	669.99
5.20	0.	0.	0.	669.99
5.25	0.	0.	0.	669.99
5.30	0.	0.	0.	669.99
5.35	0.	0.	0.	669.99
5.40	0.	0.	0.	669.99
5.45	0.	0.	0.	669.99
5.50	0.	0.	0.	669.99
5.55	0.	0.	0.	669.99
6.00	0.	0.	0.	669.99
6.05	0.	0.	0.	669.99
6.10	0.	0.	0.	669.99
6.15	0.	0.	0.	669.99
6.20	0.	0.	0.	669.99
6.25	0.	0.	0.	669.99
6.30	0.	0.	0.	669.99
6.35	0.	0.	0.	669.99
6.40	0.	0.	0.	669.99
6.45	0.	0.	0.	669.99
6.50	0.	0.	0.	669.99
6.55	0.	0.	0.	669.99
7.00	0.	0.	0.	669.99
7.05	0.	0.	0.	669.99
7.10	0.	0.	0.	669.99
7.15	0.	0.	0.	669.99
7.20	0.	0.	0.	669.99
7.25	0.	0.	0.	669.99
7.30	0.	0.	0.	669.99
7.35	0.	0.	0.	669.99
7.40	0.	0.	0.	669.99
7.45	0.	0.	0.	669.99
7.50	0.	0.	0.	669.99
7.55	0.	0.	0.	669.99
8.00	0.	0.	0.	669.99
8.05	0.	0.	0.	669.99
8.10	0.	0.	0.	669.99
8.15	0.	0.	0.	669.99
8.20	0.	0.	0.	669.99
8.25	0.	0.	0.	669.99
8.30	0.	0.	0.	669.99
8.35	0.	0.	0.	669.99
8.40	0.	0.	0.	669.99
8.45	0.	0.	0.	669.99
8.50	0.	0.	0.	669.99
8.55	0.	0.	0.	669.99
9.00	0.	0.	0.	669.99
9.05	0.	0.	0.	669.99
9.10	0.	0.	0.	669.99
9.15	0.	0.	0.	669.99
9.20	0.	0.	0.	669.99
9.25	0.	0.	0.	669.99
9.30	0.	0.	0.	669.99
9.35	0.	0.	0.	669.99
9.40	0.	0.	0.	669.99
9.45	0.	0.	0.	669.99
9.50	0.	0.	0.	669.99
9.55	0.	0.	0.	669.99
10.00	0.	0.	0.	669.99

PLEAK

NO ENERGY SPILLWAY FLOW. NO FURTHER NOTINGS MADE.

APPENDIX E

INFORMATION AS CONTAINED IN  
THE NATIONAL INVENTORY OF DAMS



# INVENTORY OF DAMS IN THE UNITED STATES

STATE	DIVISION	STATE COUNTY DIST	CONGR	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
NM	478	009 02		BAKER FLOODWATER RESERVOIR SITE II	351.9	7154.0	27 JUL 79

POPULAR NAME	NAME OF IMPONDMENT
	BAKER FLOODWATER RESERVOIR SITE II
WATER BASIN	RIVER OR STREAM
	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE
0105	TRIBUTARY BAKER RIVER
	WENT-JITH
	POPULATION
	376

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCTURAL HEIGHT	HYDRAULIC HEAD	IMPOUNDING CAPACITIES MAXIMUM NORMAL	DIST OWN FED R PRV/FED SCS A VER/DATE
WENG	1971	C	30	2	125	N N N N N N N N N N

## REMARKS

US HAS	SPILLWAY	MAXIMUM DISCHARGE (CFS)	VOLUME OF DAM (CU YD)	POWER CAPACITY INSTALLED (MW)	PROPOSED (MW)	NAVIGATION LOCKS
2	601 U	80	20326	607		

OWNER	ENGINEERING BY	CONSTRUCTION BY
N M WATER RESOURCES BD	SOIL CONSERVATION SERV	ROBIE CONSTRUCTION CO

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	NONE	NONE

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
HOWARD NEEDLES TAMMEN BERGENDOFF	17 MAY 79	PUBLIC LAW 92-367 AUG 1972

REMARKS
---------



**END**

**FILMED**

**9-85**

**DTIC**